



# G-SONORI-L-MB




# Contents Checklist

1




X1

2




X1

3




X1

4



X1


5



X1

# Contents Checklist

A



20MM


X4

B



16MM


C



X2 20MM

X4


D




16MM

X6


E




## Tools Required





## Measuring Guide




STEP 1




STEP 2






STEP 3





STEP 4



STEP 5



STEP 6



STEP 7

