



G-SONORI-H-GB




Contents Checklist

1




X1

2




X1

3




X1

4



X1


5



X1

Contents Checklist

A



20MM


X4

B



12MM

C




X2

16MM

X4


D




16MM

X6


E



Tools Required




Measuring Guide





X6


STEP 1






STEP 2






STEP 3





STEP 4



STEP 5



STEP 6



STEP 7

