## Firmware Installation Guide

# **Integrated Music Systems and Powered Studio Monitors**



#### Overview

The following describes the process for the installation of firmware for products that contain the Avatar module. While the standard update method is Over the Air (OTA) there may be times when the update may requires updating via USB.

### **Supported Products**

	L75ms Integrated Music System
ſ	4305p Powered Studio Monitor

## **Contacting Support**

Should you have any questions regarding any version of firmware or how to feel free to contact Luxury Audio Support.

Email:	luxurysupport@harman.com
Inside the US and Canada:	+1 888.691.4171
Outside the US and Canada:	+44 1707 668 012

# Over the Air (OTA) - Google Home/Airplay

The firmware is updated Over the Air (OTA) directly to the product via the Google Home or Airplay Apps. Simply open Google Home or Airplay on your device and the update will start automatically.

**Note:** This method only applies to units where setup was performed through these apps. Devices that used other methods or are not connected to the network will need to follow one of the methods below.

### **USB** Installation

### **Required Items**

- USB-A Memory Stick
- Latest Firmware File
- Product with Avatar Module
- This Installation Guide

#### **USB Installation Process**

- 1. Download the latest firmware package and un-compress folder and files.
- 2. Copy the **image.swu** file to the root directory of a USB-A memory stick.
- Ensure that the power switch is in the Off position.
  NOTE: For the 4305p ensure that both the **Primary** and **Secondary** speakers are turned **Off**.
- 4. Locate the **USB Port** on the rear of the device and Insert the USB-A memory stick into the **USB Port** on the rear of the unit to be updated.

**Note:** While similar the location of the USB and service button can vary from model to model.

5. **Press & Hold** the **Service** button while powering on the unit via the AC mains switch.

**NOTE:** For the 4305p turn on the **Primary** speaker followed by the **Secondary** speaker while continuing to hold the **Service** button.



- Continue to hold the service button for 5 seconds the LEDs change per helow
  - 4305p Front Panel LEDs will be Purple.
  - L75ms Streaming LED will be Purple.
- 7. The update process will continue and can take up to 10 minutes When completed the unit will reset automatically and return to the last selected source.

# **Verifying Firmware Version**

The version of firmware installed can be retrieved via the Google Home, Airplay, or Roon apps. Examples below.

